

Lieutenant Governor

## State of Utah DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

**Division of Oil Gas and Mining** 

JOHN R. BAZA
Division Director

October 24, 2007

Mr. John Burggraf, Vice President – Excavation Division Lakeview Rock Products, Inc. 900 North Redwood Road North Salt Lake, Ut 84054

Subject: Request for Immediate Implementation of Plan Actions, Lakeview Rock Products, Inc.,

Thomas Pit, M0110002, Davis County, Utah

Dear Mr. Burggraf:

Division personnel, Ms. Beth Ericksen visited the Thomas Pit site on October 18, 2007, which has resulted in the following request for action items associated with the permit NOI.

The table below identifies the necessary action and whether this action is affiliated with the current plan that will require an amendment (A), if the action required is a result of not following the plan (NOI) outline (I), or if the action description is suggestive only. As shown in the table, the required change is identified along with referencing the particular rule, picture number and deadline.

| Action<br>Description   | A or I | Required Change | Rule       | Picture reference | Deadline         |
|---|--------|-----------------|------------|-------------------|------------------|
| Ensure adequately sized berms are placed along upper on-site access roads | I      | Implement       | R647-4-107 |                   | November 1, 2007 |
| Improved on-site<br>upper access road<br>maintenance is<br>suggested      | S      | N/A             | R647-4-107 |                   | N/A              |

The Division considers the above-mentioned actions are plan and erosion control related. These issues can possibly be MSHA health and safety related as well. Please contact MSHA at 801-524-3450 for more information.

Please contact Ms. Beth Ericksen at 801-538-5318 once the berms have been re-established on the upper access road.

Page 2 John Burggraf M0110002 October 24, 2007

The Division appreciates and values your ongoing prompt attention to these matters. A copy of the inspection report is forthcoming under separate cover. If there are any questions regarding the content of this letter, please contact Ms. Beth Ericksen.

Sincerely,

Susan M. White

Mining Program Coordinator Minerals Regulatory Program

SMW:BE:pb

Cc: Michael Okuniewicz, MSHA, okuniewicz.michael@dol.gov